#### Work Order ID 57034 March 17, 2010 1:52:44 PM Item ID: D206-642-347 Revision ID: Item Name: Wearshoe Start Date: 3/17/10 Start Qty: 1.00 Required Date: 3/18/10 Req'd Qty: 1.00 Reference: Approvals: Process Plan: QC:

Operation

Revision Nbr

Pick Kit

Description

Memo

CHG002

Memo

Memo

Sequence ID/

Draw Nbr

Document Control

100

110

120

Packaging


Packaging

Quality Control

Work Center ID



Accept



40

	The state of the s
,× • ·	
**************************************	

Dart /	Aeros	pace l	Ltd
--------	-------	--------	-----

W/0:5	7034	1	W	ORK ORDER CHANG	ES			
DATE	STEP	Perm. Chang	PROCEDURE CH		Ву	Date Q		Approval QC Inspector
		Parts missin on applo	to Parts hist en	727: ADD MUSM' 465 - Sielosliz - Sielosliz M11369/-8	50		Prod Mgr	
10/03/17	7	D3537-1 8# 51679	Ob to B55	465 34 - Silosli7	7			
	110	03537-3 B+ 35877	9/2+1	- Swlosliz				Valenting
		m627039CI-08 M# 1918	5 97x54 3	M113691-8	105/17 31			100st 7
- 1		ANGLOCIOL MA	- Q1-1×54	1145/149CU33ZN =5	sides 17			
10/03/17	100	Fix w/s + Bom. #	ADD copy w/	updates Bon for Reg	1)	1.03.17		10/03/17
Part No	D 20	6-642-347 PAR#:	Fault Cat	egory:	NCR: Yes	No DQA:	Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C Clo	sed:	Date:	
NCR:				DER NON-CONFORMA				
DATE	STEP	Description of NC		Corrective Action Section	on B	Varificatio		L Last II.
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verificatio Section C	n Approval Chief Eng	Approval QC Inspector
								Nag Id y
The same								150
								141
1 1 1 1								

								74
			¥.		a a a			
	,•	18.						
8								

# Work Order ID 57034

March 17, 2010 1:52:44 PM



Page 2

Item ID:

D206-642-347

Accept

Setup Start

Stop



Revision ID:

Item Name:

Wearshoe

Start Date:

3/17/10

Required Date: 3/18/10

Start Qty: 1.00 Req'd Qty: 1.00

Identify and pack for shipping as per PPP D206-642-347

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start Stop

QC:

Date:

SPC (Y/N):

Date:

Run

Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Set Up/ Run Hours

0.00

Draw Number

RevA

Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

10.3.

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

Memo

Memo

0.00

10-3-17

		0 13863						
	ř							

**Picklist Print** March 17, 2010 1:52:43 PM Work Order ID: 57034 Parent Item: D206-642-347 Parent Item Name: Wearshoe Start Date: 3/17/10 Required Date: 3/18/10 Comments: IPP RevA: New issue DD verified by:EC Start Qty: 1.00 Required Qty: 1.00 Component Item ID/ Replacement Mfg/ Bin Primary Last Route Unit of Item Name Qty on Remaining Qty Date Item ID Purch Item Location Status Location Seq ID Measure Hand Qty To Pick Issued Issued D3535-11 Manufactured No Each 8.0000 Wearshoe Warehouse Loc Qty Loc Code Location Main Warehouse ST 8 46647 8 D3535-23 Manufactured Each 16.0000 10.3.17 SV Wearshoe Warehouse Loc Qty Loc Code Location Main Warehouse FP21 12 56054 12 Main Warehouse ST 53467 Manufactured Each 11.0000 10.3-17 Wearshoe Warehouse Loc Qty Loc Code Location Main Warehouse 11 51608 11

		19			
		Sec.			
					e e e e e e e e e e e e e e e e e e e
					** <u>\$</u>
					*:
		7.			
	100 g				
	× 9.				

# **Picklist Print**

March 17, 2010 1:52:43 PM

Page 2

Work Order ID: 57034

Parent Item:

D206-642-347

Parent Item Name:

Wearshoe

Comments:

IPP RevA: New issue DD verified by:EC



Start Date: 3/17/10 Start Oty: 1.00

Required Date: 3/18/10 Required Oty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID Purch

Bin Primary Location

No

Last Location

Route Seq ID

Unit of Measure

Each

Qty on Remaining Hand Oty To Pick

Otv Issued Date Issued

Status

Gasket

Warehouse Location

Warehouse

Location Main Warehouse

Main Warehouse

ST497A 46649 46715 Loc Oty

Loc Code

16,0000

10.3.17 8

Manufactured

Manufactured

10.0000 1.0000

Loc Code

Loc Code

10-3-17

D3536-35 Gasket

Manufactured

ST

10 9 Each

Loc Oty

13.0000 1,0000

10.3.17

Location Main Warehouse

Warehouse

ST 51628

13 13

Loc Qty



D206-642 Page 23 of 34

#### 206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES

Item	-311	-312	Qty -341	Qty -347	-013	Part Number	Description
	Х					D206-642-311	SKIDTUBE INSTALLATION, LH
		X				D206-642-312	SKIDTUBE INSTALLATION, RH
	1	1	X			D206-642-341	SKIDTUBE
				X	1	D206-642-347	WEARSHOE KIT (REPLACES -343)
	1	1		-	X	D206-648-013	GROUND HANDLING KIT
		<u> </u>				2200-040-013	GROUND HANDLING KIT
1			1			D2650-5	SKIDTUBE ASSEMBLY
2A	/ 17		14		()	D2651-1	* PLUG (f)
2B			14		1	D2651-3	* O-RING (1)
3			1		+	D2646	*AFT CAP (1)
4			2		1	MS27039-1-08	*SCREW(I)
5			2		+	AN960JD10L	*WASHER (1)
-			- 4		+	ANSOUSDIOL	WASHER
6	T f	-				D2932-1	SADDLE, FWD OUT, LH
6		1			1	D2932-2	SADDLE, FWD OUT, RH
7	1	-		-	_	D2933-1	
7		-		-	_		SADDLE, FWD IN, LH
	7.11	1		_	-	D2933-2	SADDLE, FWD IN, RH
8:	400	771 0			-	D2938-1	SADDLE, AFT OUT, LH
8		1				D2938-2	SADDLE, AFT OUT, RH
9	- 1	-			12	D2939-1	SADDLE, AFT IN, LH
9	10.1	1				D2939-2	SADDLE, AFT IN, RH
10	8	8				AN3-41A	BOLT
11	16	16.		1.3		D2652	BUSHING
12A	.8	8				MS21042-3	NUT (OR MS21042L3)
128	8	8				AN960JD10	WASHER
13	4	4				AN5-10A (OR AN5-11A)	* BOLT (2)
14	4	4			-		*BOLT (2)
15	8	8		_	-	AN5-11A (OR AN5-12A) AN960JD516	
				-			WASHER
16	12-	12				AN4-6A	BOLT
17	24-	24		-		AN960JD416	WASHER
18	12	12				MS21042-4	NUT (OR MS21042L4)
AGS			6		-	000000	VIETE 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10
MA .				6	-	D3537-1	WEARPAD (REPLACES D2648-3)
	_		1	1		D3537-3	WEARPAD (REPLACES D3429-1)
2A	-		1	-1-		D3535-11	WEARSHOE (REPLACES D2656-11)
28			1 ,			D3536-11	GASKET
3A			1 🧸	1		D3535-23	WEARSHOE (REPLACES D2656-23)
3B			1			D3536-23	GASKET
4A-	1.00		1	1	and the same	D3535-35	WEARSHOE (REPLACES D2656-35)
4B			1			D3536-35	GASKET
6A			54	54		MS27039C1-08	SCREW
6B			54	54		AN960C10L	WASHER
6C		_	54			ALS7-1032-130	INSERT (1)
			3707.		4	71007-1002-100	(or AKS4-1032-130, ALS4-1032-130, AELS-1032-13
30	1	1				D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
31	1	1				D3456-1	WASHER
32	1	1				D3457-1	WASHER
33	1	1				MS21043-4	NUT
14	-	-					
34	-1	1				AN4C5A	BOLT
35	1	1				AN960C416	WASHER
36	1	1				D3413-1	RING (REPLACES D2655)
37	10	10				D2712	SET SCREW
11	2	2				D2934	SADDLE SPACER
		2				D2935	SADDLE SPACER
38	2						
38	2			1 17			
38	2			- 1/2	2	D3414-041	GHW LUG (REPLACES D2659)
38	2			1/2	2	The first over the second part of the last	
38	2			100	4	AN3C37A	BOLT
38 39 10	2			10	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	The first over the second part of the last	

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D2650-5 ASSEMBLY ABOVE (2) CHOICE OF BOLT WILL DEPEND ON CROSSTUBE (SEE INSTALLATION PROCEDURE)

COPYRIGHT © 2000 BY DART AEROSPACE USA, INC →

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: N Date: 09.09.09

### Dart Aerospace Ltd W/O: WORK ORDER CHANGES Approval Approval DATE STEP PROCEDURE CHANGE Bv Qtv Date Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: Corrective Action Section B Description of NC Verification Approval Approval DATE STEP **Action Description** Sign & Initial Section A Section C Chief Eng QC Inspector Chief Eng Chief Eng Date

NOTE: Date & initial all entries

1200-642-347

Status	AN960C10L	Rev Name	Start Date	⊋uantity Pe UOM		Route Seq IE	Sort	Comments	Date Last Mod	Add Date
*	AMAGOCTOL	washer	17/03/2010	54.0000 Each	0 %	110	10	a	17/03/2010 2:27 PM	17/03/2.
1	D3535-11	Wearshoe	05/12/2009	1.0000 Each	0 %	110	3	(a)	17/03/2010 2:27 PM	
1	D3535-23	Wearshoe	05/12/2009	1.0000 Each	0 %	110	5	93	17/03/2010 2:27 PM	
8	D3535-35	Wearshoe	05/12/2009	1.0000 Each	0 %	110	7	al	17/03/2010 2:27 PM	
1	D3536-11	Gasket	05/12/2009	1.0000 Each	0 %	110	4	a Y	17/03/2010 2:27 PM	
~	D3536-23	Gasket	05/12/2009	1.0000 Each	0 %	110	6	I	17/03/2010 2:27 PM	7h 2 U
V	D3536-35	Gasket	05/12/2009	1.0000 Each	0 %	110	8	7/1	17/03/2010 2:27 PM	
8	D3537-1	Wearpad	17/03/2010	6.0000 Each	0 %	110	1	107	17/03/2010 2:27 PM	V 2
8	D3537-3	Wearpad	17/03/2010	1.0000 Each	0 %		2		17/03/2010 2:27 PM	
8	M527039C1-08	SCREW	17/03/2010	54.0000 Each	0 %		9		17/03/2010 2:27 PM 17/03/2010 2:27 PM	



BEEFER WALL